

# Operating Instructions (DT-3)

## Functions

- Indoor and outdoor temperature measure function.
- Indoor relative humidity & comfort level indicator.
- Maximum and minimum temperature and indoor humidity memory.

## Parameters

- Indoor measurement range(-30°C to 50°C).
- Outdoor measurement range(-50°C to 70°C).
- Humidity measurement range(20%RH to 99%RH).

## Operation Description

- Indoor/Outdoor Temperature & Humidity.
- ◆ In indoor temperature,press **MAX** key will display the maximum indoor temperature and maximum indoor humidity.Press **MIN** key will display the minimum indoor temperature and minimum indoor humidity.
- ◆ In outdoor temperature,press **MAX** key will display the maximum outdoor temperature and maximum indoor humidity.Press **MIN** key will display the minimum outdoor temperature and minimum indoor humidity.
- Press **RESET** key will clear the Indoor/Outdoor Temperature & Humidity memory.
- Comfort indicators will display the level as comfortable,wet or dry.The table is shown below:

